

Appendix 2 - Photographs of work in progress and following completion



Hags and bare peat on Fairsnape, 1907



Deep gullies and drip edges on Fairsnape summit, 1907



Machine reprofiling at Fairsnape, 1 Feb 2013



Fairsnape, re-profiled and re-turfed hag, 14 Feb, 2013



Hags at Holme House Fell, still in need of re-profiling, 1 Feb 2013



Example of coir log in situ on mineral soil at Holme House(from 2012 work), 14 Feb 2013



Holme House Fell re-profiled hags with geo-jute and heather brash, May 2013



Holme House Fell showing nurse crop germination in need of further lime and seed, September 2013



Gully at Fiendsdale Head to be re-profiled, 1 Feb 2013



Gully at Fiendsdale Head re-profiled with check dams in place, May 2013